

ESPL Welding Training Course

Processes Allowed at ESPL:

- *TIG (Tungsten Inert Gas)*
- *MIG (Metal Inert Gas)*
- *Oxyacetylene annealing*
- *Soldering*

Topics Covered:

1. Theory
2. Operation and Best Practices
3. Welding Safety



- No "Stick" welding
- No welding of Stainless Steel
- No welding of Galvanized Steel

Bruce Flachsbart © 2019 University of Illinois at Urbana-Champaign, All Rights Reserved

slide 1




1

To learn more thoroughly
about welding, consider
taking TSM 233, 3hrs

Welding

1. Theory




Bruce Flachsbart © 2019 University of Illinois at Urbana-Champaign, All Rights Reserved

slide 2



2

“Joining” classifications



Bruce Flachsart © 2019 University of Illinois at Urbana-Champaign, All Rights Reserved slide 3



3

Soldering and brazing

- Alternative to welding that uses a filler metal between the parts.
- The entire joining area must be heated uniformly.
- Used when:
 - Metals have *poor weldability*
 - *Dissimilar metals* are to be joined
 - Intense heat of welding may *damage* components
 - Geometry of joint not suitable for welding
 - High strength is not required
- Brazing definition: filler metal $T_m > 450^\circ\text{C}$ (840°F)
- Solder definition: filler metal $T_m < 450^\circ\text{C}$ (840°F)

Bruce Flachsart © 2019 University of Illinois at Urbana-Champaign, All Rights Reserved slide 4



4

Brazing and soldering fluxes

- They dissolve or inhibit formation of oxides on the metal surface.
- Displaced by filler metal and facilitates wetting of filler metal.
- Required by virtually all soldering/brazing methods
- Flux fumes are **very dangerous**, you must use snorkel ventilation, a fume hood, or fume capture.

Bruce Flachsbart © 2019 University of Illinois at Urbana-Champaign, All Rights Reserved slide 5



5

Soldering & brazing at ESPL

- Only lead-free solders are allowed – with vapor capture and/or ventilation of flux fumes.
- Brazing requires too high a temperature to safely teach at ESPL and is more difficult since it requires the entire joint to be very evenly heated. Find a professional to do this for you.

Bruce Flachsbart © 2019 University of Illinois at Urbana-Champaign, All Rights Reserved slide 6



6

Why no stick welding at ESPL?

- Stick welding, or SMAW, uses a *flux coated consumable electrode*, not a shielding gas to prevent oxides.
- According to OSHA, *stick flux fumes are quite noxious*:
 - MIG and TIG are less chemically dangerous because they can be done without using Flux.

ARC Welding in Decreasing Fume Production and Risk:

1. **Flux Core Arc Welding (FCAW)** filler metal electrode; flux shield
2. **Shielded Metal Arc (SMAW)** electrode provides both flux and filler material **Stick** ←
3. **Gas Metal Arc (GMAW or MIG)** widely used; consumable electrode for filler metal, external gas shield
4. **Tungsten Inert Gas (GTAW or TIG)** superior finish; non-consumable electrode; externally-supplied inert gas shield

https://www.osha.gov/Publications/OSHA_FS-3647_Welding.pdf



Bruce Flachsbart © 2019 University of Illinois at Urbana-Champaign, All Rights Reserved


slide 7

I ILLINOIS

7

MIG (Metal Inert Gas) welding

- Accounts for about 50% of all welds
- *Consumable wire electrode fed through a welding gun surrounded by an inert gas.*
- Wire metal is the same metal as part;
- *Argon gas with 25% CO₂* is required to do MIG welding at ESPL



<http://www.arcabrasives.com/Fabrication/Welding.html>

Bruce Flachsbart © 2019 University of Illinois at Urbana-Champaign, All Rights Reserved

slide 8

I ILLINOIS

8

MIG gif



Current arcs between the filler rod and the part surface carrying charged molten metal droplets with it. Filler rod has inert gas flowing around it at all times.


Bruce Flachsbart © 2019 University of Illinois at Urbana-Champaign, All Rights Reserved slide 9



9

TIG (Tungsten Inert Gas) welding

- Non consumable tungsten electrode.
- Welding can be done with or without filler metal.
- If filler metal is used, it is supplied typically as a stick.



<http://www.arcabrasives.com/Fabrication/Welding.html>

Bruce Flachsbart © 2019 University of Illinois at Urbana-Champaign, All Rights Reserved slide 10



10

TIG gif



Tungsten electrode is on the left and stays out of the molten pool. Filler rod is on right and goes in and out of molten pool. Direction is to the right.

Bruce Flachsart © 2019 University of Illinois at Urbana-Champaign, All Rights Reserved slide 11



11

Advantages and disadvantages

MIG

Pro:

- Faster welding
- Easier to learn

Con:

- Weld splatter
- Greater part distortion

TIG

Pro:

- Precision welding
(smaller spot size)
- Can do thinner parts

Con:


- More dexterity required
- Slower process

Bruce Flachsart © 2019 University of Illinois at Urbana-Champaign, All Rights Reserved slide 12




12

Types of weld joints:




Butt joint:

parts lie in same plane and are joined at their edges



Corner joint:

parts form a right angle and are joined at the corner



Lap joint:

consists of two overlapping parts


©2010 John Wiley & Sons, Inc. M P Groover, *Fundamentals of Modern Manufacturing* 4/e

Bruce Flachsart © 2019 University of Illinois at Urbana-Champaign, All Rights Reserved slide 13




13

Types of weld joints:



Tee joint:

one part is perpendicular to the other. Weld on one or both sides.



Edge joint:

parts parallel with at least one edges in common. The weld is made along the common edge.

©2010 John Wiley & Sons, Inc. M P Groover, *Fundamentals of Modern Manufacturing* 4/e


Bruce Flachsart © 2019 University of Illinois at Urbana-Champaign, All Rights Reserved slide 14



14

Typical “groove” welds on butt joints:

- One or more edges can be beveled to facilitate the weld penetration. Dashed lines show original part edges.



©2010 John Wiley & Sons, Inc.
M P Groover, *Fundamentals of
Modern Manufacturing* 4/e

- (a) no bevel; (b) one-sided bevel; (c) both parts beveled; (d) U-groove bevel;
(e) single-sided U-bevel; (f) double sided bevels for thicker parts.


Bruce Flachsart © 2019 University of Illinois at Urbana-Champaign, All Rights Reserved slide 15



15

Typical “fillet” welds

- Filler metal used to form weld creates a right-triangle cross section. Minimal edge preparation needed.



©2010 John Wiley & Sons, Inc. M P Groover, *Fundamentals of Modern Manufacturing* 4/e

- (a) inside fillet corner joint; (b) outside fillet corner joint; (c) double fillet lap joint; and
(d) double fillet tee joint.

Bruce Flachsart © 2019 University of Illinois at Urbana-Champaign, All Rights Reserved slide 16



16

Weld quality problems:

1. Residual stresses and distortion
 - Due to rapid heating and cooling of small regions
2. Welding defects
 - Cracks, slag inclusions, cavities and incomplete penetration.


Bruce Flachsart © 2019 University of Illinois at Urbana-Champaign, All Rights Reserved slide 17



17

Weld distortion

- Part material will be consumed and weld area contracts:




©2010 John Wiley & Sons, Inc.
M P Groover, *Fundamentals of
Modern Manufacturing* 4/e

Bruce Flachsart © 2019 University of Illinois at Urbana-Champaign, All Rights Reserved slide 18



18


Welding defects: incomplete fusion & distortion



19


Welding defects: cracks

- Visible after shrinkage during solidification.



20

Welding defects: cracks



Bruce Flachsart © 2019 University of Illinois at Urbana-Champaign, All Rights Reserved

slide 21


©2010 John Wiley & Sons, Inc. M P Groover,
Fundamentals of Modern Manufacturing 4/e



21

Welding defects: cavities

- Caused by incomplete fusion of parts:



Bruce Flachsart © 2019 University of Illinois at Urbana-Champaign, All Rights Reserved


slide 22

©2010 John Wiley & Sons, Inc. M P Groover,
Fundamentals of Modern Manufacturing 4/e



22

Welding defects: penetration




Bruce Flachsbart © 2019 University of Illinois at Urbana-Champaign, All Rights Reserved slide 23




23

Design advisor (i.e. green/blue are better, red is not)

Welding




Soldering



24

Weld inspection and testing

- Inspection methods – generally non-destructive
 - Visual inspection of surface for cracks and inclusions.
 - Ultrasound or x-rays to look for cracks and voids below the surface.
- Testing – generally destructive
 - Common tensile and shear tests:




©2010 John Wiley & Sons, Inc. M P Groover, *Fundamentals of Modern Manufacturing* 4/e

25

Thermal changes and weld defects

Cross section of a typical fusion welded joint: (a) principal zones in the joint, and (b) typical grain structure.




Mechanical properties are generally weaker in the HAZ (Heat Affected Zone), and this is *typically where failures occur*.


26

OxyFuel (e.g. oxyacetylene) flame temperature

Flame formed by acetylene (C_2H_2) and oxygen produces the highest flame temperature.



Oxy-acetylene flame



Neutral flame

Oxidising flame

Carburising flame

www.twi.co.uk




Table O-1
Oxyacetylene Flame Temperatures

Ratio of Oxygen to Acetylene	Type of Flame	Temperature	
		°C	°F
0.8 to 1.0	Carburizing	3065	5550
0.9 to 1.0	Carburizing	3150	5700
1.0 to 1.0	Neutral	3100	5600
1.5 to 1.0	Oxidizing	3427	6200
1.8 to 1.0	Oxidizing	3482	6300
2.0 to 1.0	Oxidizing	3370	6100
2.5 to 1.0	Oxidizing	3315	6000

27

OxyFuel (e.g. oxyacetylene) part identification



28

Oxyacetylene: lighting and setting the torch

1. Make sure **your environment is free of flammable material**
2. Open both gas cylinders, check for sufficient pressure.
3. Open "Oxy" valve on the torch, and set the output pressure of the oxygen gas to **~10 psi**.
4. Clock-wise turning, increases regulator output pressure.
5. Close "Oxy" valve on the torch, open the "fuel" valve and set the output pressure to **~5 psi**.
6. With the fuel flowing use the striker to light a flame.
7. Open "Oxy" valve and adjust to achieve a sharply defined inner cone with no outer feather.
8. **When shutting down, first close the oxygen valve.**

Bruce Flachsart © 2019 University of Illinois at Urbana-Champaign, All Rights Reserved slide 29



29

Welding

2. Operation & best practices



Bruce Flachsart © 2019 University of Illinois at Urbana-Champaign, All Rights Reserved slide 30



30

Ways to minimize weld warpage



- Use welding *fixtures* to physically restrain parts
- Use *heat sinks* to rapidly remove heat
- *Tack weld* at multiple points before seam welding
- *Preheat* base parts, primarily aluminum
- *Stress relief* by annealing after welding
- Weld material in *small increments*

Bruce Flachsbart © 2019 University of Illinois at Urbana-Champaign, All Rights Reserved slide 31



31

Pre-setting parts to prevent distortion



<http://www.twi-global.com>


Parts are pre-set by a pre-determined amount (often determined by experience) so that after welding parts are aligned correctly.

Bruce Flachsbart © 2019 University of Illinois at Urbana-Champaign, All Rights Reserved slide 32



32

Melting and heating to remove distortion



Localized heating or melting can remove buckling in thin parts, or on the backside of a fillet welds can straighten angular distortions.

Bruce Flachsbart © 2019 University of Illinois at Urbana-Champaign, All Rights Reserved


slide 33

<http://www.twi-global.com>

I ILLINOIS

33

TIG welding part identification



Bruce Flachsbart © 2019 University of Illinois at Urbana-Champaign, All Rights Reserved

slide 34

I ILLINOIS

34

TIG welding electrical settings



Typically use 1 amp
for each 0.001" of
metal thickness

Use DC for welding
steel or AC for
welding Aluminum

Bruce Flachsart © 2019 University of Illinois at Urbana-Champaign, All Rights Reserved slide 35



35

TIG and MIG ground clamp

- Completes the circuit, allows electrode to arc and allows electricity to flow through the part.
- Should be clamped as close to work piece as possible




Bruce Flachsart © 2019 University of Illinois at Urbana-Champaign, All Rights Reserved slide 36



36

TIG welding gas tank part identification



Typically gas pressure to the torch is 15-20 cubic feet per hour (cfh).

Bruce Flachsbart © 2019 University of Illinois at Urbana-Champaign, All Rights Reserved slide 37



37

Incorrect gas flow causes inclusions & porosity

- Pressure should be adjusted to achieve between 15-25 cubic feet per hour (cfh).
- Don't assume a higher rate is better. High flow rates can create turbulence that pulls in contaminants and also cause arc wondering.



Bruce Flachsbart © 2019 University of Illinois at Urbana-Champaign, All Rights Reserved slide 38



38

Gas cylinder safety

- Cylinder caps MUST be on the tank BEFORE you remove the restraining chain or move a tank without a cart.
- Never drag a cylinder - roll it back and forth to move it.
- Cylinder must always be in the upright position.
- Chains should secure tank between midpoint and top shoulder.
- Do not leave tanks in egress routes.
- Never paint a cylinder.
- Separate full tanks from empty tanks.




Bruce Flachsbart © 2019 University of Illinois at Urbana-Champaign, All Rights Reserved slide 39

I ILLINOIS

39

TIG welding torch end



Tip sticks out $\frac{3}{16}$ " to $\frac{1}{4}$ "

Keep tip about the same distance above the surface.

Steel has sharp tip,
aluminum needs a
rounded tip


Bruce Flachsbart © 2019 University of Illinois at Urbana-Champaign, All Rights Reserved slide 40

I ILLINOIS

40

Weld puddle / pool

- Will appear as a bright circle when welding and is the section of the weld that is currently liquid.
- Controlling the puddle is key to making a good weld.




Bruce Flachsart © 2019 University of Illinois at Urbana-Champaign, All Rights Reserved slide 41

I ILLINOIS

41

Filler rod

- Filler rod is coated in a protective layer but is made up of the same metal as the base part.
- Filler rod is added to the weld manually.
- Should be dipped into the puddle and quickly removed



Bruce Flachsart © 2019 University of Illinois at Urbana-Champaign, All Rights Reserved slide 42

I ILLINOIS

42

Welder setup videos

- [How to set up a TIG welding torch](https://www.youtube.com/watch?v=u8a999EIXfc)
www.youtube.com/watch?v=u8a999EIXfc
- [Holding a torch and grinding tungsten](https://www.youtube.com/watch?v=QSfeWtmWynI&t=1m22s)
www.youtube.com/watch?v=QSfeWtmWynI&t=1m22s
- [Torch angle and tip preparation](https://www.youtube.com/watch?v=tNYmo2_DI6c&t=39s)
www.youtube.com/watch?v=tNYmo2_DI6c&t=39s
- [Safety and setting up gas cylinder](https://www.youtube.com/watch?v=bWIKtsiR68w&t=52s)
www.youtube.com/watch?v=bWIKtsiR68w&t=52s

Bruce Flachsart © 2019 University of Illinois at Urbana-Champaign, All Rights Reserved slide 43



43

Welding technique videos

- [Basic TIG & MIG welding techniques](https://www.youtube.com/watch?v=VEEpikDY058&t=30s)
www.youtube.com/watch?v=VEEpikDY058&t=30s
- [TIG welding troubleshooting – too hot or cold, too far or close](https://www.youtube.com/watch?v=CVABYfuZXIY&t=113s)
www.youtube.com/watch?v=CVABYfuZXIY&t=113s
- [TIG welding troubleshooting – tungsten tip and gas flow](https://www.youtube.com/watch?v=RTH49rGzspM)
www.youtube.com/watch?v=RTH49rGzspM

Bruce Flachsart © 2019 University of Illinois at Urbana-Champaign, All Rights Reserved slide 44



44

Rules of welding

- If something seems wrong STOP, remove foot from peddle, move torch away from work part and check your setup.
- Do not let the electrode touch the work part or the weld puddle.
- Remove paint and any coating at least 1" from weld area.
- Always clamp parts tight, heat from welding causes large warpage in work part.
- To get good at welding takes a lot of practice.

Bruce Flachsart © 2019 University of Illinois at Urbana-Champaign, All Rights Reserved slide 45



45

What to do before welding

1. You **MUST** have a buddy to weld
2. Remove flammable material from your work area.
3. Check for proper PPE
4. Open argon tank gas valve
5. Securely connect ground clip to the work part
6. Check tungsten electrode length and tip cleanliness
7. Turn on welder
8. Adjust torch argon pressure

Bruce Flachsart © 2019 University of Illinois at Urbana-Champaign, All Rights Reserved slide 46



46

What to do during welding

1. Flip mask down.
2. Hold torch near part (~2 mm away)
3. Slowly step on peddle until arc starts.
4. Adjust current with foot.
5. Weld (explained on next slide)
6. When done welding, stop pressing peddle.
7. Post-flow of argon prevents contamination: HOLD TORCH OVER WELD FOR ~7 sec.

Bruce Flachsart © 2019 University of Illinois at Urbana-Champaign, All Rights Reserved slide 47



47

Welding technique best practices

1. Create weld pool and ensure proper size.
2. Slightly zig zag torch along weld path.
3. Dip filler rod into weld pool to add material as needed.
4. Take care not to melt a complete hole in work part.

Bruce Flachsart © 2019 University of Illinois at Urbana-Champaign, All Rights Reserved slide 48



48

What to do after welding

1. Close argon tank gas valve
2. Empty gas line pressure to the torch
3. Turn off welder
4. Remove ground clip from work part
5. Wait for torch and work part to cool before moving them
6. Disassemble torch and clean up

Bruce Flachsart © 2019 University of Illinois at Urbana-Champaign, All Rights Reserved slide 49



49

Welding

3. Safety

Bruce Flachsart © 2019 University of Illinois at Urbana-Champaign, All Rights Reserved slide 50



50

Dangers when welding

1. Very High Heat
2. High Electric Current
3. Very Bright Light
4. UV Radiation
5. Dangerous Fumes

Bruce Flachsbart © 2019 University of Illinois at Urbana-Champaign, All Rights Reserved slide 51



51

Biggest concern is the very high temperature

- Problem:
 - Burns
- PPE Needed:
 - Welding gloves
 - Face shield – welding helmet
 - Long sleeves
 - Pants
- Precautions:
 - Don't touch recently welded parts
 - Pay attention where your filler rod is when it is hot



Bruce Flachsbart © 2019 University of Illinois at Urbana-Champaign, All Rights Reserved slide 52



52

High temperature safety

- Problem:
 - Starting a nearby fire
- Precautions:
 - Do not weld within 10 feet of flammable cabinets.
 - Don't have any flammables within 10 feet of the welding area, including trash cans!
 - "Buddy" is on "fire watch" during welding.



https://www.osha.gov/pls/oshaweb/owadisp.show_document?p_table=STANDARDS&p_id=9853

Bruce Flachsbart © 2019 University of Illinois at Urbana-Champaign, All Rights Reserved

slide 53

I ILLINOIS

53

High electric current safety

- Problem:
 - Shocking yourself or potential electrocution.
- Precautions:
 - Always have the grounding clip on the work part.
 - Always work with a buddy, within line of sight.



Bruce Flachsbart © 2019 University of Illinois at Urbana-Champaign, All Rights Reserved

slide 54

I ILLINOIS

54

Very bright light safety

- Problem:
 - Eye damage
- PPE needed:
 - Welding helmet
- Precautions:
 - Don't look straight at someone else welding without a welding helmet



Bruce Flachsbart © 2019 University of Illinois at Urbana-Champaign, All Rights Reserved


slide 55



55

UV radiation safety

- Problems:
 - Sunburn
 - Eye damage
- PPE Needed:
 - Welding helmet
 - Long sleeves
 - Pants



Bruce Flachsbart © 2019 University of Illinois at Urbana-Champaign, All Rights Reserved

slide 56



56

Dangerous fumes safety

- Problems:
 - Lung damage
 - Cancer
 - Kidney damage
- Precautions:
 - Do only in a well ventilated area (e.g. place snorkel intake as close as reasonably possible to the welding.)



Bruce Flachsbart © 2019 University of Illinois at Urbana-Champaign, All Rights Reserved

slide 57



57

What is in welding fumes?

- Metals:
 - Aluminum, Antimony, Arsenic, Beryllium, Cadmium, Chromium, Cobalt, Copper, Iron, Lead, Manganese, Molybdenum, Nickel, Silver, Tin, Titanium, Vanadium, Zinc.
- Gases:
 - Shield gas: Argon, Helium, Nitrogen, Carbon Dioxide.
 - By products: Nitric Oxide, Nitrogen Dioxide, Carbon Monoxide, Ozone, Phosgene, Hydrogen Fluoride, Carbon Dioxide.
- Chromium is in stainless steel, and can be converted to its hexavalent state which is highly toxic.

No student welding of stainless steel or galvanized at ESPL!

https://www.osha.gov/Publications/OSHA_FS-3647_Welding.pdf

Bruce Flachsbart © 2019 University of Illinois at Urbana-Champaign, All Rights Reserved

slide 58



58

Ventilation safety

- Acute exposure to welding fumes and gases can result in *eye*, *nose* and *throat irritation*, *dizziness* and *nausea*.
- If you experience symptoms, *shut down* equipment and leave area immediately; *seek fresh air and medical attention*.

Bruce Flachsart © 2019 University of Illinois at Urbana-Champaign, All Rights Reserved slide 59



59

Welding safety summary

- Welding takes a lot of practice to master.
- Proper setup can improve welds and make learning easier.
- Welding has a number of very serious dangers:
 - Heat burns
 - Blinding light
 - Electric shock
 - Fires
 - Gas cylinders under pressure
- There is a lot to keep track of – let your buddy help to keep everyone safe!

Bruce Flachsart © 2019 University of Illinois at Urbana-Champaign, All Rights Reserved slide 60



60